

	Type	L #	Hits	Search Text	DBs	Time Stamp	Error Correction	Errors
1	IS &R	L1	1095	(351/160r,160h).C CLS.	USPAT; US-PGPUB	2003/02/0 5 14:37		0
2	BR S	L2	6189 52	channel\$4	USPAT; US-PGPUB	2003/02/0 5 14:37		0
3	BR S	L3	3948	microchannel\$4	USPAT; US-PGPUB	2003/02/0 5 14:37		0
4	BR S	L4	856	micro-channel\$4	USPAT; US-PGPUB	2003/02/0 5 14:38		0
5	BR S	L5	1091 62	duct\$1	USPAT; US-PGPUB	2003/02/0 5 14:38		0
6	BR S	L6	4849 07	groove\$1	USPAT; US-PGPUB	2003/02/0 5 14:38		0
7	BR S	L7	1047 202	2 or 3 or 4 or 5 or 6	USPAT; US-PGPUB	2003/02/0 5 14:18		0
8	BR S	L8	97	1 and 7	USPAT; US-PGPUB	2003/02/0 5 14:34		0
9	BR S	L9	6874 22	fluid\$1 or lachrymal or	USPAT; US-PGPUB	2003/02/0 5 14:39		0
10	BR S	L10	64	tear\$1 8 and 9	USPAT; US-PGPUB	2003/02/0 5 14:35		0
11	BR S	L11	33	8 not 10	USPAT; US-PGPUB	2003/02/0 5 14:35		0
12	IS &R	L12	529	(351/161,162).CC LS.	USPAT; US-PGPUB	2003/02/0 5 14:37		0
13	BR S	L13	344	12 not 1	USPAT; US-PGPUB	2003/02/0 5 14:36		0
14	BR S	L14	43	7 and 13	USPAT; US-PGPUB	2003/02/0 5 14:36		0
15	BR S	L15	20	9 and 14	USPAT; US-PGPUB	2003/02/0 5 14:36		0
16	BR S	L16	23	14 not 15	USPAT; US-PGPUB	2003/02/0 5 14:36		0

	Type	L #	Hits	Search Text	DBs	Time Stamp	Err Cor mD me e n t i o n	Er r o r s
17	IS &R	L1 7	241	(351/160r,160h).C CLS.	EPO; JPO; DERWENT	2003/02/0 5 14:37		0
18	IS &R	L1 8	58	(351/161,162).CC LS.	EPO; JPO; DERWENT	2003/02/0 5 14:37		0
19	BR S	L1 9	294	17 or 18	EPO; JPO; DERWENT	2003/02/0 5 14:37		0
20	BR S	L2 0	5805 09	channel\$4	EPO; JPO; DERWENT	2003/02/0 5 14:37		0
21	BR S	L2 1	1337	microchannel\$4	EPO; JPO; DERWENT	2003/02/0 5 14:37		0
22	BR S	L2 2	407	micro-channel\$4	EPO; JPO; DERWENT	2003/02/0 5 14:38		0
23	BR S	L2 3	1539 09	duct\$1	EPO; JPO; DERWENT	2003/02/0 5 14:38		0
24	BR S	L2 4	5696 47	groove\$1	EPO; JPO; DERWENT	2003/02/0 5 14:38		0
25	BR S	L2 5	1261 259	20 or 21 or 22 or 23 or 24	EPO; JPO; DERWENT	2003/02/0 5 14:38		0
26	BR S	L2 6	5	19 and 25	EPO; JPO; DERWENT	2003/02/0 5 14:39		0
27	BR S	L2 7	4660 0	channel\$4 with (fluid\$1 or lachrymal or tear\$1)	USPAT; US-PGPUB	2003/02/0 5 15:05		0
28	BR S	L2 8	548	microchannel\$4 with (fluid\$1 or lachrymal or tear\$1)	USPAT; US-PGPUB	2003/02/0 5 15:05		0
29	BR S	L2 9	97	micro-channel\$4 with (fluid\$1 or lachrymal or tear\$1)	USPAT; US-PGPUB	2003/02/0 5 15:06		0

	Type	L #	Hits	Search Text	DBs	Time Stamp	Err Corr mD me nti on	Er rors
30	BR S	L3 0	1628 3	duct\$1 with (fluid\$1 or lachrymal or	USPAT; US-PGPUB	2003/02/05 15:06		0
31	BR S	L3 2	2894 2	tear\$1 groove\$1 with (fluid\$1 or lachrymal or tear\$1)	USPAT; US-PGPUB	2003/02/05 15:06		0
32	BR S	L3 3	8269 2	27 or 28 or 29 or 30 or 32	USPAT; US-PGPUB	2003/02/05 14:51		0
33	BR S	L3 4	8905	contact adj lens\$2	USPAT; US-PGPUB	2003/02/05 14:51		0
34	BR S	L3 5	432	33 and 34	USPAT; US-PGPUB	2003/02/05 14:51		0
35	BR S	L3 6	1439	1 or 12	USPAT; US-PGPUB	2003/02/05 14:51		0
36	BR S	L3 7	401	35 not 36	USPAT; US-PGPUB	2003/02/05 14:52		0
37	BR S	L3 8	2256 1	channel\$4 with (fluid\$1 or lachrymal or tear\$1)	EPO; JPO; DERWENT	2003/02/05 15:05		0
38	BR S	L3 9	133	microchannel\$4 with (fluid\$1 or lachrymal or tear\$1)	EPO; JPO; DERWENT	2003/02/05 15:05		0
39	BR S	L4 0	31	micro-channel\$4 with (fluid\$1 or lachrymal or tear\$1)	EPO; JPO; DERWENT	2003/02/05 15:06		0
40	BR S	L4 1	7888	duct\$1 with (fluid\$1 or lachrymal or tear\$1)	EPO; JPO; DERWENT	2003/02/05 15:06		0

	Type	L #	Hits	Search Text	DBs	Time Stamp	Error Cor D e m e n t s	Error Cor D e m e n t s
41	BR S	L4 2	1068 5	groove\$1 with (fluid\$1 or lachrymal or tear\$1)	EPO; JPO; DERWENT	2003/02/0 5 15:06		0
42	BR S	L4 3	3972 9	38 or 39 or 40 or 41 or 42	EPO; JPO; DERWENT	2003/02/0 5 15:06		0
43	BR S	L4 4	9971	contact adj lens\$2	EPO; JPO; DERWENT	2003/02/0 5 15:07		0
44	BR S	L4 5	25	43 and 44	EPO; JPO; DERWENT	2003/02/0 5 15:07		0
45	BR S	L4 6	9	45 not us.pc.	EPO; JPO; DERWENT	2003/02/0 5 15:07		0